



---

## Customer Release Notes, September 1, 2023 (2.30.5)

Middleware and platform release September 1, 2023 (2.30.5)

### Bugs fixed in this release:

- Wireless meshing link performance is not correctly calculated.
- Chirpstack does not communicate with a LAN in Isolated mode.
- Older WiFi devices can't connect to Veeahub AP with WPA2+WPA3.
  - Starting with this release, the default is WPA2 mode.
- An AP removed from a LAN was reported as an error.
  - Now, it's not an error to disable or disassociate an AP.
- The log sometimes incorrectly indicates that a cellular connection has failed.
- The Veeahub sometimes failed to go Operational despite a working management connection.
- Enrolling a VHC25 Stacker without a SIM installed sometimes remains offline when SIM is installed later.

### Known issues in this release:

- The SW upgrade progress bar sometimes gets stuck on step 11.
  - A workaround is to upgrade again.

The following are the latest releases of software:

Veeahub Image	VHC05	VHx09	VHx10	5G HH10	VHC25
Bootloader	2.6.1	2.24.0	2.24.0	2.28.0	2.25.0
Recovery	2.30.0-29	2.30.0-29	2.30.0-29	2.30.1	2.30.1
System	2.30.5	2.30.5	2.30.5	2.30.5	2.30.5