

VeeaHub

2.33.1

Release Notes



Release Summary

This release fixes a problem with WiFi beacons on the VHx09/10 Veeahubs.

Bugs Fixed

P

Issue Summary



An issue has been identified with APs no longer transmitting beacons after a period of time. Client devices may be unable to connect to 2.4GHz SSIDs but this has also been reported for 5GHz operation. This issue affects E09/10 and VHH10 variants only.

Release Notes

The problem has been tracked to an issue handling 802.11mc FTM (Fine Timing Measurement) requests. 802.11mc operation has been disabled until the issue is fully resolved.