

VeeaHub

2.35.5

Release Notes



Release Summary

This release added two new features:

- Additional methods to the Bluetooth Config API
- Updated regulatory domain settings for Peru

It also fixed a bug with service access from Control Center.

New Features

T

Issue Summary

Release Notes



The Bluez Dbus API does not allow configuration of the BLE connection data length.

A new BluetoothConfig method (SetDataLength) was added to allow configuration of the connection data length and time. A second method was added to configure the connection Phy (SetPhy).



The Wi-Fi regulatory domain settings for Peru needs to be updated to match the latest specs.

The Wi-Fi regulatory domain settings have been updated for Peru to match the latest specs.

Bugs Fixed

P Issue Summary



Control center provides links to access services running remotely on a Veeahub network. A problem was reported for which the full set of expected service links for a remote application was not available.

Release Notes

A problem is corrected on the Veeahub if a local port is not provided when configuring the remote link. A change in an earlier release incorrectly enforced the need to specify a port. However, a port can be omitted and in this case, the system now correctly selects the port to be used.