Customer Release Notes, August 11, 2023 (2.30.4)

Middleware and platform release August 11, 2023 (2.30.4)

Bugs fixed in this release:

- Invalid backhaul priority configuration applied to VeeaHub after Cellular un-subscribe

- Node Manger shows invalid configuration for Ethernet Port 1 on MEN

- Stability and performance issues in a mesh operating without internet access

- IPv4 address lost when 5G stacker reselected from a 5G to a 4G cell.

- VeeaHub crashes and reboots after sending BLE advertisements longer than 29 bytes

Software versions

The following are the latest releases of software:

VeeaHub Image	VHC05	VHx09	VHx10	5G HH10	VHC25
Bootloader	2.6.1	2.24.0	2.24.0	2.28.0	2.25.0
Recovery	2.30.0-29	2.30.0-29	2.30.0-29	2.30.1	2.30.1
System	2.30.4	2.30.4	2.30.4	2.30.4	2.30.4