



Customer Release Notes, May 28, 2021 (M18)

This document describes the main features of the Milestone 18 release.

Changes in this release

802.11r: Improved handover times between Veeahub Wi-Fi APs across the vMesh. The Veeahub Manager and Node Manager include this.

iFree APN: Improvements to connection to iFree APN.

3rd party SIM support: New package to support Veeahubs with non-iFree SIMs.

vTPN: Back-end changes, including to 4G support.

Software versions

The following are the latest releases of software.

Component or service	Release
Veeahub Platform	2.18.0
Enterprise Centre	1.12.7
Node Manager	1.21.14
Veeahub Manager (Android)	2.12.0
Veeahub Manager (iOS and iPadOS)	2.12.0
Control Center	2.8.0
Veeahub Toolkit	0.8.0-1-3 (no change)
vBus	1.4.12 (no change)
LoRaWAN	1.3.8 (no change)
vTPN Security Service	2.17.0



Documentation

The following documentation will be added or updated.

Document	Version	Changes
Veeahub Manager Guide	3.6	802.11r and some enhancement of screens
Node Manager Guide	1.5	802.11r
Enterprise Center Guide	1.8	Minor updates
Control Center web page	-	Added section on the 'No Veeahubs' screen, and some minor updates
IoT Device Manager web page	-	Updates to LoRaWAN and Data Broker

Customer bug fixes

None in this release.