



---

## Customer Release Notes, May 18, 2021 (M17, Hotfix 3)

This document describes the main features of the Milestone 17 Hotfix 3.

### Changes in this release

**Veeahub 2.17.3:** Self-signed containers working over a bootstrap

**vBus 1.4.12:** Further Bluetooth improvements

### Software Versions

The following are the latest releases of software.

Component or service	Release
Veeahub Platform	2.17.3 (third hotfix)
Enterprise Centre	1.11.4 (no change)
Node Manager	1.20.4 (no change)
Veeahub Manager (Android)	2.11.0 (no change)
Veeahub Manager (iOS and iPadOS)	2.11.0 (no change)
Control Center	2.6.0 (no change)
Veeahub Toolkit	0.8.0-1 (no change)
vBus	1.4.12
4G LTE Wireless WAN backup	2.17.0 (no change)
LoraWan	1.3.8 (no change)
vMenu	1.6.5 (no change)
vTPN	2.16.0-6 (no change)



---

## Documentation

No documentation will be added or updated.

## Customer bug fixes

None in this hotfix