



Customer Release Notes, July 18, 2021 (2.20.0)

Release effective July 18, 2021

This document describes the main features of the release.

Service Impact

On Sunday July 18, 2021, Control Center will be unavailable from 12:00pm to 2:00pm EDT for scheduled maintenance. After this time, please upgrade your Veeahub Manager to the latest version.

If you were logged into Control Center during this time, please log out and log back in.

Changes in this release

Wired Mesh - wireless islands: Provides zero-touch configuration of remote Wi-Fi vMesh clusters of Veeahubs connected to main mesh through a wired connection.

Wired Mesh - throughput performance: Improved wired mesh performance through reduction of control data transfer.

iFree vSIM Support: Improved operation of iFree 4G connections using software SIM.

Group Ownership : Group software facility for users who organize their meshes in groups to manage their meshes in groups.

Software versions

The following are the latest releases of software.

Component or service	Release
Veeahub Platform	2.20.0
Enterprise Centre	2.1.12
Node Manager	1.23.1
Veeahub Manager (Android)	3.0.0



Component or service	Release
Veeahub Manager (iOS)	3.0.0
Control Center	2.10.0
Veeahub Toolkit	0.8.2-1 (no change)
vBus, IoT Device Manager	1.4.18 (no change)
LoRaWAN Chirpstack	1.4.4 (no change)
vTPN Security Service	2.17.0 (no change)
4G Failover (iFree SIM)	2.17.0 (no change)
4G Failover (Third-party SIM)	2.19.0 (no change)

Documentation

The following documentation will be added or updated.

Document	Version	Changes
Node Manager Guide	1.6	Wired mesh and wired islands functionality, Group ownership set up
Veeahub Manager Guide	3.7	Wired mesh and wired islands functionality, Group ownership set up
Control Center		Wired mesh and wired islands functionality, Group ownership set up