



Customer Release Notes, October 30, 2022 (2.28)

Platform release October 30

Changes in this release

- 5G support in H10-5G outdoor
- Enhanced 4G connection reliability
- C25 WDS WiFi Mesh support for 3 nodes.
- Throughput performance improvements

Changes in this release for Developers

- vBus support for VHC25

Software versions

The following are the latest releases of software:

Veeahub Image	VHC05	VHE09	VHE10	VHH10	VHC25
System	2.28	2.28	2.28	2.28	2.28
Recovery	2.26.0-6	2.26.0-6	2.26.0-6	2.28.0	2.26.0-6

Component software releases

Component	Released Version
Enterprise Centre	3.1.2
Node Manager	1.30.4
VHM android	3.6.0 (146) - 3abfedb
VHM ios	3.6.0 (12)



Component	Released Version
VH Services	1.27.0
VH Billing Service	1.16.280
Control Center	3.2.0-887be63a-2022.07.28.12.08.40
Node-Shadow Collector	0.1.193

Application

Application	Base Release
Veea vBus IoT + IoTMgr	vBus 1.6.1 + IoTMgr 3.0.1
Veea Home Assistant (integrated with vBus)	1.0.10
4G Failover (iFree)	2.20.0
4G Failover (3rd Party SIM)	2.19.0
Veea LoRaWAN ChirpStack	1.4.4
vMenu	1.6.5
vTPN (PNEC)	2.22.2 (PNEC module 1.5.14)
vTPN Security Service	2.22.2 (PNEC module 1.5.14)
vTPN with 4G LTE Wireless WAN Broadband	2.22.2 (PNEC module 1.5.14)
Veeahub System Monitoring Tool	2.0.1 (no change)
AdEdge	2.3.4
Veea Azure IoT Edge	1.1 (LTS)
Tridium Niagara	0.0.4

